

Delph INS Subsea 3.12.1 Release Notes

These Release Notes detail improvements and bug fixes from Delph INS version 3.12.0 to Delph INS 3.12.1
Please read these notes carefully before installing the software.

1 What's new

1.1 Bug Fixes

- > Swap of divisor/multiplier in export template editor
- > Wrong USBL #2 transponder name after decoding
- > Incorrect warning message when calibrating with USBL position sensor
- > OpenStreetMap tiles display near the map borders

1.2 Improvements

- > QA/QC report supports USBL #3

2 Customer Support

For any additional questions feel free to contact our worldwide 24/7 customer service:

By e-mail: support@exail.com

By phone:

+33 (0) 1 30 08 98 98 for EMEA

+1 617 861 4589 for the North America / NORAM

+65 6747 7027 for Asia