

Delph INS subsea 3.7.0 Release Notes

These Release Notes detail improvements and bug fixes from Delph INS version 3.6.0 to Delph INS 3.7.0. Please read these notes carefully before installing the software.

1 What's new

1.1 Improvements

- > Exail graphic design interface
- > 64bits software configuration
- > Exail certificate signing
- > Trajectory direction on plan view

1.2 Bug Fixes

- > Variable panel refresh after processing
- > Atmospheric pressure sensor error
- > Wrong density unit
- > LBL transponder enable/disable
- > Speed values computing on trajectory separation
- > Time scale filtering on plan view

2 Customer Support

For any additional questions feel free to contact our worldwide 24/7 customer service:

By e-mail: support@exail.com

By phone:

+33 (0) 1 30 08 98 98 for EMEA

+1 617 861 4589 for the North America / NORAM

+65 6747 7027 for Asia